

April 2021

MAINTENANCE OF POWDER COATED SURFACES

We recommend that powder coated surfaces are cleaned with a non-abrasive cleaner every six months. If the surfaces accumulate a lot of dirt, cleaning should take place more frequently. Common detergents with pH values between 5 and 9 are suitable for the cleaning.

To remove dirt from large surface areas, you can use, for example, a pressure washer with emulsifying detergent. Detergents must not contain any abrasives or solvents. Mechanical wash involving brushing could damage the paint finish. After washing, rinse the paint surface with plenty of water and dry it thoroughly.

When cleaning paint surfaces with special shades, such as texture, structure, and metallic effects, you should check the suitability of the washing solution on a small area in an inconspicuous place before cleaning larger areas.

For further information, please contact your local Teknos representative.