

EPITAN 92

Epoxy tank coating

Modified epoxy primer, flake materials pigmented, thixotropic, high solid, two component, cured in low temperatures (from -10°C).

For priming of steel constructions operating in sea, coastal, technical and fresh water, underwater parts of ships, docks and hydrotechnical constructions.

For self-protection of ballast and sewage tanks, steel constructions operating in water or in ground (canal locks, culverts, weirs, dolphins, tanks, pipelines, quays, Larsen walls, etc.)

Coating with outstanding adhesion to surfaces, resistant to acid and alkali solutions, water and marine environment, aggressive atmospheric conditions, soil and elements occurring in the cathodic protection.



TECHNICAL DATA

Fields of application	Pipelines, Steel constructions, Submerged constructions, Subterranean constructions, Storage tank
Recommended substrate	Steel
Binder	Epoxy
Solids	72±2% by volume (ISO 3233)
Total mass of solids	Approx. 1300 g/l
Volatile organic compound (VOC)	Approx. 300 g/l (DIRECTIVE 2010/75/EU) The VOC value provided is the average value for factory produced products, and consequently it will be subject to variations between individual products covered by this Technical Data Sheet.

Theoretical spreading rate	Dry film (µm)	Wet film (µm)	Theoretical spreading rate (m²/l)
	150	208	4.8
	175	243	4.1

As many of the paint's properties will change if too thick coats are applied, it is not recommended that the product is applied to a film thickness that is more than double of the thickest recommended film.

Practical spreading rate The values depend on the application technique, surface conditions, overspray, etc.

Colours	TO-990 black
Gloss (60°)	Semi-matt
Hardener	Comp. B: UTWARDZACZ 076/077/087/EPITAN 92

Mixing ratio (A:B)	100:18 parts by volume
Pot life, +23 °C	3,5 h
Thinner	TEKNOSOLV 9506, TEKNOSOLV 564
Storage	The storage stability is shown on the label. Store in a cool place and in tightly closed containers.

DIRECTION FOR USE

Surface preparation	<p>Before cleaning of surface, it is recommended to wash it with water with addition of OLICLEAN 123 and then rinse with fresh water. The surfaces are prepared according to the different materials as follows:</p> <p>STEEL SURFACES: The surface to be treated must be dry, salt-, grease- and dust-free, cleaned to the degree of cleanliness according to ISO 8501-1: Sa 2½ for submerged areas or at least St 3 for external surfaces. For internal surfaces at least Sa 2½. Porous surfaces should be primed with thinned EPITAN 92 paint. Coating gets the highest mechanical and chemical resistance by applying directly to sandblast cleaned steel surfaces (cleanliness at least Sa 2½).</p> <p>COATING OF EPOXY PAINT: The surface to be treated must be without any rust, dry, salt-, grease- and dust-free.</p> <p>Additional instructive information for surface preparation can be found in standards EN ISO 12944-4 and ISO 8501-2.</p>
Application method	Airless spraying, Brush

Application

Take into consideration the pot life of the mixture when estimating the amount to be mixed at a time. Before application the base and hardener are mixed in right proportion. Stir thoroughly down to the bottom of the vessel. Mixing by machine is recommended, for example a slow-rotating hand-drill equipped with a mixer. Inadequate stirring or incorrect mixing ratio results in imperfect curing and impaired film properties.

Apply by airless spray or brush. When using a brush it may be necessary to apply several layers to achieve recommended coating thickness.

Airless spray parameter:

Nozzle size 0.48 - 0.63 mm

Nozzle pressure 20 - 25 MPa

When preparing painting specification, depending on subject and type of construction, different dry film thickness than recommended can be assumed. During airless spray application typical dry film thickness range is between 150 and 250 µm. Different dry film thickness than recommended causes change in theoretical spreading rate, wet film thickness, weight of dry film thickness, drying time, overcoating time and ready for handling time.

In high corrosive environment it is recommended to prepare surface as best as possible and to apply successive layers of paint before full curing of previous layers to achieve best protection.

Application conditions

During the application and drying period the temperature of the ambient air shall be above -10°C, of the paint should be over +15°C and the relative air humidity below 95%. The minimum temperature of the surface shall be above -5°C (frost- and ice-free surface) and at least 3°C higher than dew point of the ambient air. Adequate ventilation during application and drying period is recommended.

