


INERTA 51

Epoxy paint

INERTA 51 is a two-pack solvent-borne epoxy paint.



SSG 1021-GA



The paint film is very dense and provides good resistance to water and chemicals. The paint has good resistance to heat - even damp heat.

APPROVALS:

The paint comes up to the specifications of Swedish Standard SSG 1021-GA.

TECHNICAL DATA

classification

Certificates, approvals and

Recommended substrate	Steel, Concrete				
Binder	Ероху				
Solids	50 ±2% by volume				
Total mass of solids	Approx. 970 g/l				
Volatile organic compound (VOC)	Approx. 440 g/l (Theoretica	prox. 440 g/l (Theoretical) (DIRECTIVE 2010/75/EU)			
	Approx. 298 g/l (Tested according to China GB/T 23985-2009)				
	The VOC value provided is t	he average value for fact	ory produced products, and		
	consequently it will be subject to variations between individual products covered by this TDS.				
Theoretical spreading rate	Dry film (µm)	Wet film (µm)	Theoretical spreading rate (m²/l)		
	50	100	10.0		
	80	160	6.2		
	100	200	5.0		
	125	250	4.0		
	As many of the paint's properties will change if too thick coats are applied, it is				
	not recommended that the product is applied to a film thickness that is more				
	than double of the thickest recommended film.				
Practical spreading rate	The values depend on the application technique, surface conditions, overspray, etc.				
Colours	White and grey.				
Gloss (60°)	Semi-matt				



Hardener	Comp. B: INERTA PRIMER 3/INERTA 51 HARDENER
Mixing ratio (A:B)	4:1 parts by volume
Pot life, +23°C	6 h
Thinner	TEKNOSOLV 9506
Storage	The storage stability is shown on the label. Store in a cool place and in tightly
	closed containers.

DIRECTION FOR USE

preparation

Remove from the surfaces any contaminants that might be detrimental to surface preparation and application. Remove also water-soluble salts by using appropriate methods. The surfaces are prepared according to the different materials as follows:

STEEL SURFACES: Remove mill scale and rust by blast cleaning to preparation grade Sa $2\frac{1}{2}$ (standard ISO 8501-1). Roughening the surface of thin-plate improves the adhesion of the paint to the substrate.

CONCRETE SURFACES: The concrete must be at least 4 weeks old, well-hardened and solid. The water content of the top layer must not exceed 4% by weight.

Smooth down any spatter and irregularities on the surfaces by grinding. Brush away loose cement, sand and dust. Wash oily and greasy surfaces with detergent or solvent. Remove dense laitance if present by etching with RENSA ETCHING etching liquid or by grinding or blast-cleaning.

OLD PAINTED SURFACES SUITABLE FOR OVERCOATING: Any impurities that might be detrimental to the application of paint (e.g. grease and salts) are removed. The surfaces must be dry and clean. Old, painted surfaces that have exceeded the maximum overcoating time are to be roughened as well. Damaged parts are prepared in accordance with the requirements of the substrate and the maintenance coating.

The place and time of the preparation are to be chosen so that the prepared surface will not get dirty or damp before the subsequent treatment.

Additional instructive information for surface preparation can be found in standards EN ISO 12944-4 and ISO 8501-2.

Prefabrication primer: KORRO E Epoxy Prefabrication Primer can be used, when required.

Application method

Airless spraying



Δ	D	D	li	ca	ıti	o	n
_	_	~	••			•	

MIXING OF THE COMPONENTS: Take into consideration the pot life of the mixture when estimating the amount to be mixed at a time. Before application the base and hardener are mixed in right proportion. Stir thoroughly down to the bottom of the vessel. Inadequate stirring or incorrect mixing ratio results in imperfect curing and impaired film properties.

Stir thoroughly before use.

Apply preferably by airless spray as only this method provides the recommended film thickness in a single operation. Suitable airless nozzle size 0.017 - 0.021". Brush can be used for touching up and painting small areas.

The surface to be treated must be dry. During the application and drying period the temperature of the ambient air, the surface and the product shall be above

Additionally, the temperature of the surface to be treated and the product must be at least +3°C above the dew point of the ambient air.

Drying time $+23^{\circ}\text{C} / 50\% \text{ RH (dry film 50 } \mu\text{m)}$

- dust free 1 h (ISO 9117-3:2010) - touch dry 5 h (ISO 9117-5:2012)

- fully cured 7 d

Overcoatable

Application conditions

surface temperature	OBJECTS IN A	ERTA 50, FOR TMOSPHERIC SURE	by itself or INERTA 50, FOR SUBMERGED OBJECTS	
	min.	max.*	min.	max.*
+10°C	12 h	6 months	36 h	7 d
+23°C	4 h	6 months	12 h	7 d

^{*} Maximum overcoating interval without roughening.

+10°C and the relative air humidity below 80%.

Increase in film thickness and rise in the relative humidity of the air in the drying space usually slow down the drying process.

Cleaning TEKNOSOLV 9506

HEALTH AND SAFETY

Safety and precaution measures See safety data sheet.

Teknos Group Oy Takkatie 3, P.O.Box 107 FI-00371 Helsinki, Finland Tel. +358 9 506 091

The above information is normative and based on laboratory tests and practical experiences. The information is noncommittal, and we cannot accept liability for the results obtained under working conditions beyond our control, and consequently the buyer or the user is not released from the obligation to test the suitability of our products for specific means and application methods under the actual application conditions. Our liability covers only damage caused directly by defects in the products supplied by Teknos. This product is intended for professional use only. This implies that the user possesses sufficient knowledge for using the product correctly with regard to technical and working safety aspects. The latest versions of Teknos' Technical Data Sheets and Safety Data Sheets are available from our homepage www.teknos.com. All trademarks displayed on this document are the exclusive property of Teknos Group or its affiliated companies.